

clt ring Ø57 installation instruction




the chosen luminaire tech specs for required height and free air dimensions.

Mill a round hole with the above dimensions. Consult



place the clt ring in the hole like shown above



the fixture can now be installed

thank you for choosing prado

Installation must be done by skilled professionals only and instructions must be followed at all times. Warranty will not apply in case of wrongful

use of if unskilled personnel attempts to repair a product.